Request for Quotations for Repair of wood work at Punjab Information & Communication Technology Corporation Ltd Office situated at 5<sup>th</sup> & 6<sup>th</sup> Floor Udyog Bhawan, Sector 17 Chandigarh

The Corporation has desired to repair the wood work at its 5th & 6<sup>th</sup> floor behind reception from the reputed contractors. The vendor may visit the location (Punjab Infotech, 5<sup>th</sup> & 6<sup>th</sup> Floor Udyog Bhawan Sector 17 Chandigarh) for inspection on any working day from 10:00am to 4 PM.

### Scope of Work

The agency is required to replace the deteriorated wood work paneling installed at the backside of the reception at 6<sup>th</sup> floor of its corporate office. The detailed repair work is as under;

\_\_\_\_\_\_

6<sup>th</sup> Floor - Repair

	Cost performa to be filled by the agency					
Sr. No.	Description	Qty	unit	Rate	Amount	
1	Providing and fixing GI Framing for Cusin and Fixing Ply consisting Ceiling Section (80 mm with tapered flanges of 26 mm each having lips of 10.5 mm, at 450 mm centre to centre), with the help of Nylon sleeve and Wooden Screw to the entire satisfaction	33.78	sft	<>	<>>	
2	Providing and fixing Flush Door 35mm thick, fix with help of 5" SS Hings Edge		no	<>	<>	
3	Providing and fixing of veener 3.5mm paneling fix with favicol and nails also finish with melamine polish to the entire satisfaction of the Corporation	ding and fixing of veener 3.5mm ing fix with favicol and nails also finish nelamine polish to the entire  47.50 sft <>		<>		

	Providing and fixing 12mm Ply for the				
	existing base with the help of wooden				
4	screw using fevicol and required nails	33.78	sft	<b>&lt;&gt;</b>	<>
	complete in all respect and entire				
	satisfaction of the Corporation				
	Providing and melamine polish in natural				
5	5 Shade to the entire satisfaction of the		sft	<>	<>
Corporation					
Sub Total A					<b>&lt;&gt;</b>

# Measurements :-

Item No. 3						
Providing and fixing of veener 3.5mm paneling fix with fevicol and nails also finish with melamine polish to the entire satisfaction						
Sr	·					
no.	Location	Length	Width	Area		
1	Washroom Front	7.16	2.25	16.11		
2	Door	6.6	2.08	13.73		
3	Washroom Front II	4.33	4.08	17.67		
			sft	47.50		

	Item No. 1 & 4					
Providing and fixing 12mm Ply for the existing base with the help of wooden screw using fevicol and required nails complete in all respect and entire satisfaction						
Sr						
no.	Location	Length	Width	Area		
1	Washroom Front	7.16	2.25	16.11		
2	Washroom Front II	4.33	4.08	17.67		
			sft	33.78		

Item No. 5					
Provid	Providing and melamine polish in natural Shad to the entire satisfaction				
Sr Sr					
no.	Location	Length	Width	Area	

1	Washroom Front	7.16	2.25	16.11
2	door	6.5	2.08	13.52
3	Washroom Front II	4.33	4.08	17.67
4	5th floor washroom	7.16	18.92	135.47
			sft	182.76

\_\_\_\_\_

# 5<sup>th</sup> Floor Repair

	Cost performa to be filled by the agency				
Sr. No.	Description	Qty	unit	Rate	Amount
	Providing and fixing GI Framing for Cusin				
	and Fixing Ply consisting Ceiling Section				
	(80 mm with tapered flanges of 26 mm				
1	each having lips of 10.5 mm, at 450 mm	86	sft	<b>&lt;&gt;</b>	<b>&lt;&gt;</b>
	centre to centre), with the help of Nylon				
	sleeve and Wooden Screw to the entire				
	satisfaction				
2	Providing window (34 inc x 48 inches)	1	no	<>	<>
	Providing and fixing of veener 3.5mm				
	paneling fix with fevicol and nails also finish				
3	with melamine polish to the entire		sft	<b>&lt;&gt;</b>	<>
	satisfaction of the Corporation				
	Providing and fixing 12mm Ply for the				
	existing base with the help of wooden				
4	screw using fevicol and required nails	86	sft	<>	<b>&lt;&gt;</b>
	complete in all respect and entire				
	satisfaction of the Corporation				
	Providing and melamine polish in natural				
5	Shade to the entire satisfaction of the	300	sft	<b>&lt;&gt;</b>	<b>&lt;&gt;</b>
	Corporation				

	Item No. 1					
Providing and fixing of veener 3.5mm paneling fix with fevicol and nails also finish with melamine polish to the entire satisfaction						
Sr						
no.	Location	Length	Width	Area		
1	Wall 01	86	26			
2	Wall 02	49	53			
3	Wall 03	78	37	53.06 sq ft		
4	Wall 04	54	85	33 sq ft		
			Inch	86 sq ft		

	Item No. 5					
	Window measurements to be fixed with Veener 3.5 mm paneling fix with fevicol and nails also finist with melamine polish to the entire area					
Sr						
no.	Location	Length	Width	Area		
	Window size with two					
1	panels	34	48	12 sq ft		
			Inch	12 sq ft		

## **Selection of the Agency:**

The interested parties may submit their best possible rates after due examining the work in a sealed envelope by writing of the top "Repair of Wood Work – Admin" on or before August 13, 2019 at the Corporate office Sector 17 Chandigarh.

The rates are to be submitted as per the performa given below.

The bidder with the lowest rates will be selected for the work. The agency will be required to complete the work within 10 days from the order.

-----/-----/-----

#### Format For the submission of the Rates

(To be	submitted ir	n sealed	envelope	writing of	the top	" Repair	of Wood	Work -
Admin"	on or before	August 1	3, 2019 at	the Corpo	orate offic	e Sector 1	7 Chandig	jarh.)

To,

The Managing Director Punjab Infotech

Dear Sir,

We have gone through the request for Quotations for Repair of wood work at Punjab Information & Communication Technology Corporation Ltd Office and after due diligence the best possible rates are as under;

Items	Value
Sub Cost A (6 <sup>th</sup> Floor Cost)	
Sub Cost B (5 <sup>th</sup> Floor Cost)	
Any other Charges	
GST	
Total Value of the work	

Thanking you

Yours faithfully

Sign and Stamp